

Service Bulletin

File in Section:

Bulletin No.: 16-NA-093

Date: April, 2016

TECHNICAL

Subject: Vehicle Remote Start Inoperative, Malfunction Indicator Lamp (Check Engine Light) ON

with P3055 and/or P3056 Set

Models: 2016 Chevrolet Malibu

Equipped with Stop/Start (RPO KL9)

Attention: This Bulletin also applies to any of the models that may be Israel Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Біапи.	woder.	from	to	from	to		
Chevrolet	Malibu (VIN Z)	2016	2016	SOP	GF245872	All	All

Condition	Some customers may comment that the Remote Vehicle Start is inoperative, the Malfunction Indicator Lamp (Check Engine Light) is ON and the Stop/Start function is inoperative. Upon an initial GDS2 scan check, DTC P3055 and/or P3056 are set in the K20 Engine Control Module.
Additional Options	Equipped with Stop/Start (RPO KL9).

Service Procedure

Vehicles that have DTC P3055 and/or P3056 should follow SI diagnostics.

Diagnostics leading to replacement of the T19 Power Supply Transformer (Multifunction Power Supply Converter) should use the listed labor operation code.

Parts Information

Description	Part Number	Qty
CONVERTER, M/FUNC PWR SPLY	13514044	1

Warranty Information

Labor Operation	Description	Labor Time
4041350	Multifunction Power Supply Converter Replacement	Use Published Labor Operation Time

Version	2
Modified	April 14, 2016 – Changing the Labor Operation from 5420210 to 4041350.